



SNO KONE MACHINE

OPERATION

1. Start the motor and fill the gooseneck to an inch from the top with either ice cubes or 3" x 4" pieces of ice. (The larger the ice pieces, the better the snow).
2. Push ice down against the cutter head with firm pressure for best snow.
NOTE: too much pressure will give you coarse ice; too little pressure and the ice will be mushy.
3. Do not force the handle.
4. A surface temperature of 150°F is normal.
5. Do not put anything other than ice in the gooseneck to prevent damage to the blades.
6. Keep fingers away from shaver body when motor is running to prevent injury.

CLEANING

Unplug the machine.
Wipe all surfaces clean and dry.

OPTIONAL SUPPLIES

Sno Kone syrup - blue raspberry, cherry, grape and lemon.
Sno Kone pump - one pump = one 1 oz serving.

NOTE: ½ lb of ice = 1 Sno Kone
1 oz of syrup = 1 Sno Kone



CAUTION



ALWAYS unplug the equipment before cleaning.
NEVER place your hand or any other object into the machine while it is in operation.
The machine MUST be properly grounded to prevent electrical shock.